2013 BMW Z4 35is

SUSPENSION Rear Axle - Repair - Z4




Fig. 11: Identifying Trolley Jack Courtesy of BMW OF NORTH AMERICA, INC.

WARNING: The vehicle may be raised with a trolley jack only at the following jacking points!

- 1. Car jacking point
- 2. Side car jacking points
- 3. Rear differential (**REMOVE HEAT SHIELD**)

Risk of damage: It is not permitted to raise the vehicle at the rear differential cover!

4. Bolting point for rear axle tension struts




Fig. 12: Identifying Rear Differential, Side Car Jacking Points And Car **Jacking Point**

Courtesy of BMW OF NORTH AMERICA, INC.